Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	106	ZERBINI-S ZERBINI-SARAH	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/09/30 18:10
S2	22	ZERBINI-S ZERBINI-SARAH	US-PGPUB; USPAT	OR	ON	2004/09/16 21:13
<b>S3</b>	11	MERASSI-A MERASSI-ANGELO	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/09/16 21:14
S4	3	MERASSI-A MERASSI-ANGELO	US-PGPUB; USPAT	OR	ON	2004/09/16 21:15
<b>S</b> 5	12	SPINOLA-DURANTE-G SPINOLA-DURANTE-GUIDO	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/09/16 21:16
S6	3	SPINOLA-DURANTE-G SPINOLA-DURANTE-GUIDO	US-PGPUB; USPAT	OR	ON	2004/09/16 21:17
·S7	0	DE-MASI-B DE-MASI-BIAGIO	USPAT	OR	ON	2004/09/16 21:18
S8	7	DE-MASI-B DE-MASI-BIAGIO	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/09/16 21:18
S9	2	DE-MASI-B DE-MASI-BIAGIO	US-PGPUB; USPAT	OR	ON	2004/09/16 21:19
S10	22	S2 S4 S6 S9	US-PGPUB; USPAT	OR	ON	2004/09/16 21:19
S11	22	S1 S3 S5 S8	US-PGPUB; USPAT	OR	ON	2004/09/16 21:20
S12	106	S1 S3 S5 S8	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/09/16 22:04
S13	84	S12 not S11	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/09/16 21:20
S14	0	circuit same contiunity	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/09/16 21:21
S15	1	circuit same discontiunity	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/09/16 21:22

S16	47088	circuit same break	US-PGPUB; USPAT;	OR	ON	2004/09/16 21:22
			EPO; JPO; DERWENT			
S17	2023	circuit same break and "200"/\$.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR .	ON	2004/09/16 23:16
S18	38	circuit same break and "200"/\$.ccls. and frangible	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/09/16 21:23
S19	0	circuit same break and "200"/\$.ccls. and frangible and aceleration	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/09/16 21:23
S20	2	circuit same break and "200"/\$.ccls. and frangible and acceleration	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/09/16 21:27
S21	2216	mems and acceleration	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/09/16 21:31
S22	14	cellphone and warranty	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/09/16 21:29
S23	0	cellphone same warranty	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/09/16 21:29
S24	3	mems adj accelerators	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON -	2004/09/16 21:39
S25	4	("6212026" "6272901").pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/09/16 21:58
S26	7	("6212026" "6272901")	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/09/16 21:58
S27	1	"4856318".PN.	USPAT; USOCR	OR	ON	2004/09/16 22:01
S28	1	"5844772".PN.	USPAT; USOCR	OR	ON	2004/09/16 22:02

			T			
S29	904	impact near detector	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/09/16 22:05
S30	0	S12 and S29	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/09/16 22:05
S31	17	200/61.08.ccls. and 200/61.45r-61. 45m.ccls.	USPAT	OR	ON	2004/09/16 22:06
S32	0	200/61.08.ccls. and 200/61.45r-61. 45m.ccls. and circuit\$2 near (fragile or frangible)	US-PGPUB; USPAT; USOCR	OR	ON	2004/09/16 22:08
S33	4	200/61.08.ccls. and 200/61.45r-61. 45m.ccls. and circuit\$2 near (break or broken)	US-PGPUB; USPAT; USOCR	OR	ON	2004/09/16 22:27
S34	2	("4116132" "2802073").pn.	USPAT	OR	ON	2004/09/16 22:19
S35	7	"2806915"	US-PGPUB; USPAT; USOCR	OR	ON	2004/09/16 22:26
S36	8911	(weak or weakened) near (region or area or surface)	US-PGPUB; USPAT; USOCR	OR	ON	2004/09/16 22:29
S37	1047	(weak or weakened) near (region or area or surface) same (groove or notch)	US-PGPUB; USPAT; USOCR	OR	ON	2004/09/16 22:30
S38	565	(weak or weakened) near (region or area or surface) with (groove or notch)	US-PGPUB; USPAT; USOCR	OR	ON .	2004/09/16 22:30
S39	24	(weak or weakened) near (region or area or surface) with (groove or notch) and mems	US-PGPUB; USPAT; USOCR	OR	ON	2004/09/16 22:56
S40	13	(weak or weakened) near (region or area or surface) with (groove or notch) same mems	US-PGPUB; USPAT; USOCR	OR	ON	2004/09/16 22:35

"6209285" "6352476" "6381290" "8331610" "567036" "8121608" "4298795" "4433982" "4812786" "4865746" "5528366" "5531959" "5526110" "5528366" "5531959" "5526110" "5528366" "5531959" "5526299" "651885" "561931" "6736036" "5760299" "6134944" "6139734" "6194716" "6252225" "6469297" "6583409" "6596989" "6469297" "6583409" "6396037" "4465227" "43748591" "4318706" "6157699" "449578" "4318706" "6157699" "449578" "4318706" "4386518" "4468742"),pn.  543  50  (*4495292" "4594884" "4615221" "4630229" "4698848" "4615221" "4959022" "4498778" "4545957" "47595992" "4594888" "5291081" "5339170" "5287438" "5291081" "5339170" "5287438" "5291081" "53399876" "6016463" "533488" "5657401" "567578" "5715046" "5330230" "534057" "5436754" "53399879" "5717212" "579869387" "5898370" "59885879" "598376" "6016463" "6031478" "6036091" "6040816" "6118127" "6124748" "6129894") pn.  544  65  circuit same break and "200"/61.08, 61.4.ccls. and (groove or notch or recess or mark)  545  36  circuit same break and "200"/61.08, 61.4.ccls. and (groove or notch or recess or mark)  549  113882 scott  USPAT  OR  ON  2004/09/16 23:32  S50  501  200/61.08  USPAT  OR  ON  2004/09/16 23:33						T	
"4595992" "4594884" "4615221" "4630229" "4860271" "4862259" "4977806" "5022172" "5195012" "5239170" "5287438" "5291081" "5399230" "534957" "5384476" "5390230" "534957" "5367544" "5534997" "5552623" "5633488" "5657401" "5675778" "5715046" "5736874" "5748593" "5777212" "5789913" "5805017" "5808994" "5831683" "5837139" "5848040" "5869987" "5998796" "6016463" "6031478" "6036091" "6040816" "6118127" "6124748" "6129894") .pn.  S44	S42	49	"6209285" "6352478" "6381290" "5331160" "5670054" "6121608" "4298795" "4433982" "4812786" "4865746" "4883958" "4958529" "5419208" "5472598" "5482628" "5526110" "5528366" "5531959" "5604299" "5651885" "5651931" "5736036" "5760299" "6134944" "6139734" "6194716" "6252225" "6329652" "6358716" "6437327" "6469297" "6583409" "6596989" "6646256" "6747272" "6774359" "5332191" "4627287" "4318706" "6157699" "4495417" "4563637" "5453246" "4275453" "4286637"	USPAT	OR	ON	2004/09/30 20:34
S45   36   Circuit same break and "200"/61.08, 61.4.ccls. and (groove or notch or recess or mark)   US-PGPUB; USPAT; EPO; JPO; DERWENT   USPAT; EPO; JPO; DERWENT   USPAT   OR ON 2004/09/16 23:34	S43	50	("4495292" "4498778" "4545957" "4595992" "4594884" "4615221" "4630229" "4860271" "4862259" "4977806" "5022172" "5195012" "5239170" "5287438" "5291081" "5349464" "5355215" "5384476" "5390230" "5434057" "5436754" "5534997" "5552623" "5633488" "5657401" "5675778" "5715046" "5736874" "5748593" "5777212" "5789913" "5805017" "5808994" "5831683" "5837139" "5848040" "586987" "5893870" "5895879" "5935255" "5966034" "5991037" "5998796" "6016463" "6031478" "6036091" "6040816" "6118127"	USPAT	OR	ON	2004/09/30 20:36
61.4.ccls. and (groove or notch or recess or mark)	S44	65	circuit same break and "200"/61.08,	USPAT; EPO; JPO;	OR	ON	2004/09/16 23:17
S50         501         200/61.08         USPAT         OR         ON         2004/09/16 23:34           S51         76         S49 and S50         USPAT         OR         ON         2004/09/16 23:34	S45	36	61.4.ccls. and (groove or notch or	USPAT; EPO; JPO;	OR .	ON	2004/09/16 23:32
S50         501         200/61.08         USPAT         OR         ON         2004/09/16 23:34           S51         76         S49 and S50         USPAT         OR         ON         2004/09/16 23:34	S49	113882	scott	USPAT	OR	ON	2004/09/16 23:34
S51 76 S49 and S50 USPAT OR ON 2004/09/16 23:34							
			•				
( N	S52	16	"3822369"	USPAT	OR	ON	2004/09/16 23:40

S63	50	("4406158" "6264893" "5216243"	USPAT	OR	ON	2004/09/30 20:32
		"5415784" "6262161" "6362270" "6566652" "4882938" "5286363"				
		"5287056" "5818598" "6394942"				
		"6417510" "6432311" "6454938"				
		"6461516" "6646213" "6301330"				
		"4581578" "5504009" "6099744"				
		"6358316" "5798778" "5909465"				
		"6038435" "5925886" "6546799"				
	``	"6577975" "5932792" "4351657"				
		"6306594" "6284277" "4307730"				
		"5468452" "6370954" "4854308"				
		"6104493" "4489521" "4918628"				
		"5206518" "5417206" "5513878"				į
		"4616754" "5548652" "6464866"				
		"4839872" "4874942" "4992656"				
		"5594803" "6101373").pn.			į.	
S64	451020	("4406158" "6264893" "5216243"	USPAT	OR	ON	2004/09/30 20:32
		"5415784" "6262161" "6362270"				
		"6566652" "4882938" "5286363"				
		"5287056" "5818598" "6394942"				
		"6417510" "6432311" "6454938"				
		"6461516" "6646213" "6301330"				
		"4581578" "5504009" "6099744"				
		"6358316" "5798778" "5909465"				
		"6038435" "5925886" "6546799"		i		
		"6577975" "5932792" "4351657"				
		"6306594" "6284277" "4307730"		ļ		
		"5468452" "6370954" "4854308"				
`		"6104493" "4489521" "4918628"		1		
		"5206518" "5417206" "5513878"				
		"4616754" "5548652" "6464866"				,
		"4839872" "4874942" "4992656"				
		"5594803" "6101373").pn. and				
		breakage or damage				
S65	11	("4406158" "6264893" "5216243"	USPAT	OR	ON	2004/09/30 20:33
		"5415784" "6262161" "6362270"				
		"6566652" "4882938" "5286363"				
		"5287056" "5818598" "6394942"				
		"6417510" "6432311" "6454938"				
	•	"6461516" "6646213" "6301330"		}		
		"4581578" "5504009" "6099744"				
		"6358316" "5798778" "5909465"				
		"6038435" "5925886" "6546799"				
-		"6577975" "5932792" "4351657"				
		"6306594" "6284277" "4307730"				
		"5468452" "6370954" "4854308"				
		"6104493" "4489521" "4918628"				
		"5206518" "5417206" "5513878"				
		"4616754" "5548652" "6464866"				
		"4839872" "4874942" "4992656"				
Ì		"5594803" "6101373").pn. and				
1		(breakage or damage)				

665		(1644227611 1644207611 162222711		0.0	011	2004/00/20 20 5
S66	0	("6113276" "6119850" "6209285" "6209285" "6352478" "6381290" "5331160" "5670054" "6121608" "4298795" "4433982" "4812786" "4865746" "4883958" "4958529" "5419208" "5472598" "5482628" "5526110" "5528366" "5531959" "5604299" "5651885" "5651931" "5736036" "5760299" "6134944" "6139734" "6194716" "6252225" "6329652" "6358716" "6437327" "6469297" "6583409" "6596989" "6646256" "6747272" "6774359" "5332191" "4627287" "4318706" "6157699" "4495417" "4563637" "5453246" "4275453" "4286637" "4386518" "4468742").pn. and ((breakage or damage) and warranty)	USPAT	OR	ON	2004/09/30 20:34
S67	11	("6113276" "6119850" "6209285" "6209285" "6352478" "6381290" "5331160" "5670054" "6121608" "4298795" "4433982" "4812786" "4865746" "4883958" "4958529" "5419208" "55472598" "5482628" "5526110" "5528366" "5531959" "5604299" "5651885" "5651931" "5736036" "5760299" "6134944" "6139734" "6194716" "6252225" "6329652" "6358716" "6437327" "6469297" "6583409" "6596989" "6646256" "6747272" "6774359" "5332191" "4627287" "4318706" "6157699" "4495417" "4563637" "5453246" "4275453" "4286637" "4386518" "4468742").pn. and (breakage or damage)	USPAT	OR	ON	2004/09/30 20:35
S68	2	("4495292" "4498778" "4545957" "4595992" "4594884" "4615221" "4630229" "4860271" "4862259" "4977806" "5022172" "5195012" "5239170" "5287438" "5291081" "5349464" "5355215" "5384476" "5390230" "5434057" "5436754" "5534997" "5552623" "5633488" "5657401" "5675778" "5715046" "5736874" "5748593" "5777212" "5789913" "5805017" "5808994" "5831683" "5837139" "5848040" "5869987" "5893870" "5895879" "5935255" "5966034" "5991037" "5998796" "6016463" "6031478"	USPAT	OR	ON	2004/09/30 20:36
		"6036091" "6040816" "6118127" "6124748" "6129894") .pn. and (breakage or damage)				

S71	4	73/12.04-12.07.CCLS. AND BREAKAGE AND DROP\$3	USPAT	OR	ON	2004/09/30 21:08
S72	419	73/12.01,12.04-12.07.CCLS.	USPAT	OR	ON	2004/09/30 21:11
S73	34	73/12.01,12.04-12.07.CCLS. AND DROPPING	USPAT	OR	ON	2004/09/30 21:15
S74	0	"73"/\$.CCLS. AND MEMS AND (IMPACT NEAR TESTING) SAME BREAKAGE	USPAT	OR	ON	2004/09/30 21:16
S75	0	MEMS AND (IMPACT NEAR TESTING) SAME BREAKAGE	USPAT	OR .	ON	2004/09/30 21:17
S76	. 0	MEMS AND ((IMPACT NEAR TESTING) SAME BREAKAGE)	USPAT	OR	ON	2004/09/30 21:17
S77	6	MEMS AND (IMPACT NEAR TESTING)	USPAT	OR	ON	2004/09/30 21:20
S78	1	"340"/\$.CCLS. AND MEMS AND (IMPACT NEAR TESTING)	USPAT	OR	ON	2004/09/30 21:21
S79	3	"340"/\$.CCLS. AND MEMS AND BREAKAGE	USPAT	OR	ON	2004/09/30 21:25
S80	4	"5949342"	USPAT	OR	ON	2004/09/30 21:29
S81	18	340/652.CCLS. AND "200"/\$.CCLS.	USPAT	OR	ON	2004/09/30 21:45
S82	1	379/1.01-35.ccls. and cellphone	USPAT	OR	ON	2004/09/30 21:45
S83	4	379/1.01-35.ccls. and circuit near discontinuity	USPAT	OR	ON	2004/09/30 21:47
S84	2	cellphone and inertial near sensor	USPAT	OR	ON	2004/09/30 21:49
S87	0	cellphone and (inertial near sensor) and (break\$3 near circuit)	USPAT	OR	ON	2004/09/30 21:50
S88	2	cellphone and (inertial near sensor)	USPAT	OR	ON	2004/09/30 21:50
S89	66	cellphone and ( sensor)	USPAT	OR	ON	2004/09/30 21:52
S90	66	cellphone and sensor	USPAT	OR	ON	2004/09/30 21:52
S91	2	cellphone and circuit and continuity	USPAT	OR	ON	2004/09/30 21:53
S92	1	cellphone and circuit same continuity	USPAT	OR	ON	2004/09/30 21:54
S93	1989	break and circuit same continuity	USPAT	OR	ON	2004/09/30 21:55
S94	598	break same circuit same continuity	USPAT	OR	ON	2004/09/30 22:35
S95		break same circuit same continuity and cellphone	USPAT	OR	ON	2004/09/30 21:55
S96	10	break same circuit same continuity and mems	USPAT	OR	ON	2004/09/30 22:20
S97	1	break same circuit same continuity and mems AND "455"/\$.CCLS.	USPAT	OR	ON	2004/09/30 22:21
S98	7	break same circuit same continuity AND "455"/\$.CCLS.	USPAT	OR	ON	2004/09/30 22:21